TELETYPE CORPORATION Skokie, Illinois, U.S.A.

INSTRUCTIONS FOR INSTALLING 402936 MODIFICATION KIT THAT PROVIDES A REPLACEABLE RIBBON SHIELD ON MODEL 40 80-COLUMN TRACTOR FEED PRINTERS

1. GENERAL

1.01 This modification kit when installed on a printer provides an improved method for replacing the ribbon shield. To replace an existing 402753 ribbon shield, it is necessary to remove and disassemble the front frame assembly. With the new 402798 ribbon shield w/eyelets installed, the front frame assembly need not be disassembled or removed from the printer if replacement becomes necessary.

1.02 The new ribbon shield wraps around the right and left ribbon guides making it virtually impossible to install the ink ribbon on the wrong side of the ribbon shield.

1.03 The new ribbon shield is translucent, having a white color, making it easy to see when installing a new ink ribbon.

1.04 The new ribbon shield has been designed to be less susceptible to damage than the 402753 ribbon shield, thus providing protection to the copy from ink smudge.

1.05	The	4029 36	modification	kit	consists	of	the	following	parts:
------	-----	----------------	--------------	-----	----------	----	-----	-----------	--------

Qty	Part No.	Description
1	88891	Spring
1	402 7 98	Ribbon shield w/eyelets
1	40281 7	Guide, right
1	402822	Spacer

2. INSTALLATION

DANGER: REMOVE ALL POWER FROM THE SET BEFORE PERFORMING ANY DISASSEMBLY AND INSTALLATION.

• Remove printer from the cabinet and place on a suitable working surface.



TYPE CARRIERS

Printed in U.S.A.



Left Arm Assembly -- Removal

• Place the printer in a vertical position with front of printer facing up.



Front Plate Assembly Parts -- Removal



Front Plate Assembly Parts -- Removal (Cont)

1

(



- (3) Reassemble the following, by reversing the removal procedures.
 - Front Plate Assembly Parts -- Steps (1) and (2)
 - Front Plate and Rear Guide Assemblies
 - Left Arm Assembly
- Ribbon Feed Assembly

Installation of New 402798 Ribbon Shield



(4) Reassemble the type carrier.

<u>Note:</u> In reassembling, start type carrier at the left pulley. Rotate type carrier one revolution by turning impeller gear by hand <u>clockwise</u>. At the same time, align any protruding type pallets against the left pulley flange.





IMPELLER GEAR

WARNING: DAMAGE TO THE TYPE CARRIER OR PRINTER WILL RESULT IF ANY PROTRUDING TYPE PALLET IS LEFT UNCHECKED.

③ Reinstall top guide plate assembly, tighten thumb screws.

Ocheck adjustment requirement on the following page.

⑦Install new or retained ink ribbon.

(3) Hook the 88891 spring through the eyelet of ribbon shield and the other end over the post of the 402626 right arm assembly. <u>Check</u> to see that the ribbon shield is straight between the ribbon guides and that it is below the hammer bank.

3. ADJUSTMENTS

LEFT AND RIGHT RIBBON GUIDE (Preliminary)

Note: The ribbon guide adjustment will be changed as follows:

Requirement: The right and left ribbon guides, with the ribbon shield between, should touch the adjusting gauge.

To Adjust: Loosen mounting screws, push the right and left ribbon guides so that the ribbon shield contacts the adjusting gauge. Tighten the mounting screws.



(Side View)

(Side View)

3. ADJUSTMENTS (Cont) LEFT AND RIGHT RIBBON GUIDES (Final) Requirement 1 There should be a Min. 0.010 inch clearance between the ribbon shield where it contacts the ribbon guides and the face of a flag pallet on carriers having three fonts and the face of a font identification pallet on carriers having two fonts. To Adjust Loosen ribbon guide mounting screws friction tight. Position guide to meet requirement. Tighten mounting screws. Repeat procedure with other ribbon guide. Requirement 2 There shall be a Min. 0.006 inch clearance between the ribbon shield where it contacts the ribbon guides and all pallet faces. To Adjust Seat pallets against rear surface of font flange of left sprocket. MOUNTING RIBBON SCREW SHIELD RIBBON PALLET (See Req. 1 SHIELD and Req. 2) ши SPRING MOUNTING SCREWS RIGHT RIBBON LEFT RIBBON GUIDE GUIDE MOUNTING SCREW (Side View) (Side View) Note: Check all adjustments that may have been disturbed.

Note: Check all adjustments that may have been disturbed Refer to Section 582-210-700 or Manuals 352 or 355.

•The ribbon feed drive belt tension.

•The paper positioner final.

4. LUBRICATION

None

Page 8 8 Pages