

TP162361 RECTIFIER ASSEMBLY

APPARATUS AFFECTED: 28G, 28L, 28LB, 28M Electrical Service Units.

OBJECT: To make the rectifier fuse more readily accessible for maintenance purposes.

CHANGE: The TP162361 rectifier assembly is reoriented and mounted so that the fuse mounting is towards the front of the unit when the unit is mounted in a set.

IDENTIFICATION: See "CHANGE". On old style units, the fuse mounting is in back of the transformer.

INTERCHANGEABILITY: Not affected.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: Not affected.

APPLICATION TO APPARATUS IN THE FIELD: Old style units may be modified to facilitate maintenance.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units shall have this change applied.