RTTY ELECTRONICS TELETYPE=Sales-Service-Parts PO Box 20101 El Sobrante, Ca. 94820. (510)222-3102 mr_rtty@pacbell.net

TELETYPE CORPORATION Skokie, Illinois, U.S.A.

SPECIFICATION 50829S Issue 5, February 1982

INSTRUCTIONS FOR INSTALLING 405671, 407024, 407025 OR 407026 MODIFICATION KITS TO THE 40CAB351/YZ AND ZZ OR 40CAB353/YZ AND ZZ COMMON CABINET CORE TO FORM THE VARIOUS ARRANGEMENTS LISTED BELOW

40 CABINET CODE (Table Top)	YZ OR ZZ + MOD. CODE KITS		DESCRIPTION	ТҮРЕ
CAB351/AB =	CAB351/ CAB351/ CAB351/	407026 407025 407024	RO Printer RO Printer W/ Provision for Opcon RO Printer W/ Provision for Opcon	80 Column Tractor (SSI) 80 Column Tractor (SSI) 80 Column Tractor (EIA)
i '. I	CAB353/ CAB353/	405671 407024	RO Printer RO Printer W/ Provision for Opcon	132 Column Tractor (SSI) 132 Column Tractor (EIA)

NOTE: 40CAB351YZ and 353YZ cabinets are similiar to 40CAB351ZZ and 353ZZ cabinets with the exception that the YZ cabinets are modified with a larger cut-out to allow dual EIA mounting. The cut-out is located in the Left rear of cabinet.

1. GENERAL

- 1.01 This specification provides necessary information for installing any of above listed modification kits into their respective cabinet core to complete the desired cabinet code.
- 1.02 All instructions on unit packing cartons and labels shown inside the cabinets should be adhered to.
- 1.03 Complete descriptions and parts identification for cabinets CAB351 and CAB353 can be found in Section 582-212-700 or Manual 355 as an aid for location and identification.
- 2. MODIFICATION KITS PARTS LISTING
- 2.01 Following is a list of parts of the four modification kits that are required to make the completed cabinet codes.
- 405671 Modification Kit

Part No.	Description	<u>Qty</u>	Part No.	<u>Description</u>	<u>Qty</u>
3640	Lockwasher	2	405609	Clip, ground	1
107116	Lockwasher	2	405644	Plate w/	
151631	Screw, 6-40 hex	2		adhesive	1
326023	Screw, 4-40 hex	2	407075	SSI signal	
402449	Bushing	2		input assembly	1

2. MODIFICATION KITS PARTS LISTING (cont)

2.01 Following is a list of parts of the four modification kits that are required to make the completed cabinet codes.

entral de la companya de la companya

407024 Modification Kit

Part No.	Description	Qty	Part No.	Description	Qty
3640	Lockwasher	2	405669	Shield	1
107116	Lockwasher	4	407012	Adhesive strip	2
116793	Lockwasher	2	407076	Capacitor	
151631	Screw, 6-40 hex	4		assembly	1
154249	Screw, #8	1	407077	EIA signal	
312918	Tie, cable	1		input assembly	1
326023	Screw, 4-40 hex	2	407301	Opcon cable	
346696	Shield	1		assembly	1
347333	Latch, Arm Assem.	1	407303	SSI cable	
347334	Latch, Arm Assem.	1		${\sf assemb1y}$	1
401227	Tab, terminal	1			
402449	Bushing	2			

407025 Modification Kit


Part No.	Description	Qty	Part No.	Description	<u>Qty</u>
3640	Lockwasher	2	403964	Opcon cable	
107116	Lockwasher	2		assembly	1
116793	Lockwasher	2	405609	Clip, ground	1
151631	Screw, 6-40 hex	2	407075	SSI signal	
154249	Screw	1		input assembly	1
326023	Screw, 4-40 hex	2			
401227	Tab, terminal	1			
402449	Bushing	2			

407026 Modification Kit

Part No.	Description	<u>Qty</u>	Part No.	Description	Qty
3640	Lockwasher	2	405609	Clip, ground	1
107116	Lockwasher	2	407075	SSI signal	
151631	Screw, 6-40 hex	2		input assembly	1
326023	Screw, 4-40 hex	2	403828	Plate Adhesive	1
402449	Bushing	2			


INSTALLATION

3.01 Installation of 405671 modification kit requires the following steps:




3.02 Installation of 407024 modification kit requires the following steps:

NOTE: If cabinet being Modified is 40CAB351/YZ or 40CAB351/zz, the Left and Right Latch Arms may have to be changed. See identification and Installation instructions on Pages 9 & 10.



3.02 (Cont)

CAUTION: When mounting capacitor assembly make sure the ribbon cable of 407077 EIA signal input assembly is clear and not pinched under capacitor bracket.




(5) Some cabinets may have a latching mechanism on connector bracket.

Temporarily disconnect spring from upper post of bracket. If "ac" power and "cabinet control" connectors are installed in the connector bracket, remove them. Use a screwdriver to press in ears.


(a) Install terminals of the 407076 capacitor assembly (407302 power cable) into ac power connector (341691).

LEGEND:

- Wires shown solid are supplied with the cabinet.
 Wires shown open are part of modification kit and are field installed.
- Numbers shown solid are marked on connector.
- Numbers circled are not marked on connector but are included for reference.




(Rear View AC Power Connector)




(Front View of Cradle Bracket)

① Insert connector of 407301 opcon cable into left front of cabinet as shown. Make sure keys face up.



(1) Attach 312918 cable tie to secure cables.





(1) Assemble two 116793 lockwashers, a 401227 terminal tab and a 154249 screw, exactly as shown.



(1) Mark cabinet identification plate with 407024 Modification Kit number.

Note: The 346696 shield must be mounted to 40K001 opcon connector when used with this modification kit. If not present refer to the 4 steps on the following page.





② Fold 346696 shield approximately along the indicated area to assist in installation.

③ Viewing terminal end of connector as shown, place left then right slotted holes over the left and right ears of the connector.

LEFT


BOTTOM

RIGHT

(Left View) (Right View)

(Bottom View)

4 With all the tabs folded, insert the connector with shield into its mounting bracket so that the tabs of the shield go through the bracket.




<u>Note</u>: Troubleshooting information for this modification kit can be found in Installation and Servicing Manual 360, Part 4.

NEW LEFT AND RIGHT LATCH ARM INSTALLATION INSTRUCTIONS FOR 40CAB351 SERIES CABINET - 80 COLUMN -

CAUTION: Do not remove right latch arm until new left latch arm is completely installed. Cradle is under great spring tension and could spring up abruptly. causing serious injury to service personnel.


Left and right cradle latches released (pressed inward):

①Remove existing TP403787 left latch arm by first releasing tension on the spring. Use appropriate spring hook.




- ②Remove TP403789 screw, TP403889 spring and T0110126 lockwasher.
- ③Using 3/4 inch open end wrench remove TP403814 shoulder screw.
- Remove Early Design TP403784 left latch arm and replace with Late Design TP347334 left latch arm. Reassembly by reversing installation instructions.
- (5) After Late Design TP347334 left latch arm is installed, right side may be dismantled and new latch may be installed following instruction for left side previously explained.

 (Ref TP403792)




NOTE: Refer to Page 10 for Early and Late Design Part Identification.

LATE AND EARLY DESIGN LATCH ARM IDENTIFICATION




LATE DESIGN LATCH ARMS




EARLY DESIGN LATCH ARMS

3.03 Installation of 407025 modification kit requires the following steps:




CAUTION: INSTALL SIGNAL CABLE CONNECTOR WITH CUT CORNER TO RIGHT AND FOUR TERMINALS IN CONNECTOR MUST BE SEATED ON RIGHT SIDE AS SHOWN. REINSERT MIDDLE CONNECTOR.


(4) Install 405609 clip by sliding it over the left edge of the cabinet opening.




(3) Assemble two 116793 lockwashsers, a 401227 terminal tab and a 154249 screw, exactly as shown.



(a) Mark cabinet identification plate with 407025 Modification Kit number.




3.04 Installation of 407026 modification kit requires the following steps:



MIDDLE CONNECTOR.

Page 13

①Install 405609 clip by sliding it over the left edge of the cabinet opening.



(3) Mark cabinet identification plate with 407026 Modification Kit number.

