

CHANGES AND ADDITIONS
TO PARTS BULLETINS
TYPE BAR PAGE PRINTER
(MODEL 15)

1037, ISSUE 4, PAGE 12
1094, ISSUE 2, PAGE 10
1110, ISSUE 2, PAGE 10
1114, ISSUE 1, PAGE 13

THE 74281 TYPE BAR BACKSTOP ASSEMBLY HAS BEEN REPLACED BY A 114188 TYPE BAR BACKSTOP ASSEMBLY ON 100 W.P.M. MACHINES AND DIFFERS AS SHOWN IN THE SKETCH BELOW:

SCREWS ARE NOT INTERCHANGEABLE BETWEEN THE TWO STYLE PARTS.

ALTHOUGH BOTH STYLE PARTS CAN BE USED INTERCHANGEABLY (WITH THE PROPER SCREWS), IT HAS BEEN FOUND THAT THE BALANCE OF LIFE IS IN FAVOR OF LEATHER FOR THE SLOWER SPEEDS AND IN FAVOR OF THE PLASTIC AT THE HIGHER SPEED.

CARBON TETRACHLORIDE, COMPOUNDS OF THIS SOLVENT, OR WATER SHOULD NOT BE USED IN CLEANING UNITS HAVING THE PLASTIC BACKSTOPS AS THEY CAUSE DETERIORATION OF THE PLASTIC MATERIAL.

FOR UNITS OPERATING AT 100 W.P.M.

FOR UNITS OPERATING AT 60 AND 75 W.P.M.

