

Table 5-4. Index of Low-Level Schematic and Wiring Diagrams for Troubleshooting

Figure	Diagram No.	Title	Page
5-7	2900 WD	Wiring Diagram; Model 28 CPP Motor Units LMU37 and LMU51	5-25
5-8	8728 WD	Wiring Diagram; Model 28 CPP KSP (Less Cover and Printer)	5-39
5-9	8729 WD	Schematic Diagram; Model 28 CPP KSP	5-41
5-10	8176 WD	Schematic Diagram; Model 28 CPP RO	5-43
5-11	8177 WD	Wiring Diagram; Model 28 CPP RO Cover LPC 402	5-45
5-12	8764 WD	Wiring Diagram; Model 28 CPP KSP Cover IPC 403	5-47
5-13	8137 WD (Sheet 1 of 3)	Wiring Diagram; Model 28 CPP RO ESA 321231 (Sheet 1 of 3)	5-49
	8137 WD (Sheet 2 of 3)	Wiring Diagram; Model 28 CPP RO ESA 321231 (Sheet 2 of 3)	5-51
	8137 WD (Sheet 3 of 3)	Wiring Diagram; Model 28 CPP RO ESA 321231 (Sheet 3 of 3)	5-53
5-14	8178 WD	Schematic Diagram; Model 28 CPP RO ESA 321231	5-55
5-15	321290	Assembly Drawing; Model 28 CPP KSR and RO ESA Power Supply Circuit Board Assembly with Heat Sink	5-57
5-16	321130 (Sheet 1 of 2)	Circuit Board Assembly; Model 28 CPP KSR and RO ESA Power Supply (47 - 53 VDC, 0.5 Amp Max) (Sheet 1 of 2)	5-59
	321130 (Sheet 2 of 2)	Circuit Board Assembly; Model 28 CPP KSR and RO ESA Power Supply (47 - 53 VDC, 0.5 Amp Max) (Sheet 2 of 2)	5-61

Table 5-4. Index of Low-Level Schematic and Wiring Diagrams for Troubleshooting - Continued

Figure	Diagram No.	Title	Page
5-17	323810	Circuit Board Assembly; Model 28 CPP KSR and RO ESA SMD with Signal Combiner	5-63
5-18	8143 WD	Schematic Diagram; Model 28 CPP KSR and RO ESA SMD with Signal Combiner, 323810	5-65
5-19	8724 WD (Sheet 1 of 4)	Wiring Diagram; Model 28 CPP KSR ESA 323120 (CMD) (Sheet 1 of 4)	5-67
	8724 WD (Sheet 2 of 4)	Wiring Diagram; Model 28 CPP KSR ESA 323120 (CMD) (Sheet 2 of 4)	5-69
	8724 WD (Sheet 3 of 4)	Wiring Diagram; Model 28 CPP KSR ESA 323120 (CMD) (Sheet 3 of 4)	5-71
	8724 WD (Sheet 4 of 4)	Wiring Diagram; Model 28 CPP KSR ESA 323120 (CMD) (Sheet 4 of 4)	5-73
5-20	8725 WD	Schematic Diagram; Model 28 CPP KSR ESA 323120 (CMD)	5-75
5-21	333069	Assembly Drawing; Model 28 CPP KSR ESA CMD Circuit Board Assembly with Heat Sink	5-77
5-22	333142	Schematic Diagram; Model 28 CPP KSR ESA CMD Circuit Board Assembly	5-79
5-23	8726 WD (Sheet 1 of 3)	Wiring Diagram; Model 28 CPP KSR FSA 323121 (SMD and LLK) (Sheet 1 of 3)	5-81
	8726 WD (Sheet 2 of 3)	Wiring Diagram; Model 28 CPP KSR ESA 323121 (SMD and LLK) (Sheet 2 of 3)	5-83
	8726 WD (Sheet 3 of 3)	Wiring Diagram; Model 28 CPP KSR ESA 323121 (SMD and LLK) (Sheet 3 of 3)	5-85
5-24	8727 WD	Schematic Diagram; Model 28 CPP KSR ESA 323121 (SMD and LLK)	5-87

Table 5-4. Index of Low-Level Schematic and Wiring Diagrams for Troubleshooting - Continued

Figure	Diagram No.	Title	Page
5-25	323130	Schematic Diagram; Model 28 CPP KSP ESA LLK Circuit Board Assembly	5-89
5-26	8179 WD	Wiring Diagram; Model 28 CPP RO Base LLB 5	5-91
5-27	8242 WD	Wiring Diagram; Model 28 CPP RO Typing Unit LP 139	5-93
5-28	8299 WD	Wiring Diagram; Model 28 CPP RO Typing Unit Selector Assembly 319204	5-95
5-29	8763 WD	Wiring Diagram; Model 28 CPP KSR Typing Unit LP 156	5-97