

INDEX TO ELECTRON VOLUME 7

PART I • ALPHABETICAL

Adjusting the AFC in the SU Receiver.....	May 15	Letters to the Editor	Jan. 27
An Electronic Preventive Maintenance Program...	May 1	Letters to the Editor	Feb. 32
Classification of Radar Sets	May 29	Letters to the Editor	Mar. 32
Correction to NAVSHIPS 98081 FC No. 18-QGB...	May 28	Loctal Tubes for Shipboard Facsimile Equipment.	Mar. 23
Electron Tube Users Can Increase Tube Life.....	May 18	Loss of SS Crystal Current	Feb. 30
1952 Electronics Conference at the Bureau of Ships	May 25	Magnetic Recorder which Provides Resolution of	
ESO Monthly Column	May 14	Signal Energy Printed Through the Medium by	
Failure of Transformer T-802 and Choke L-804 in		Means of a Variable Scan Rate Pickup (USN	
Model AN/SPS-6 Radar	May 27	USL Notes)	Mar. 18
Field Change No. 1-AN/APR-9A, Inversion of		Maintenance of Antenna Assembly AS-393 (XN-	
Video Output Pulse	May 9	1)/BLR	Jan. 12
Field Engineer Sez	May 16	Maintenance Parts for Submarine Signal Company	
Index to Electron Volume 7.....	May 30	896 Commercial Fathometers	Mar. 23
Letters to the Editor	May 32	Mark 10 Radar Identification System.....	Apr. 18
List of Naval Electronic Equipment	May 31	Mark 10/IFF (Field Engineer Sez).....	Apr. 8
New Books	May 26	Mark 25/2 (Field Engineer Sez).....	Apr. 9
QHB-a Primary Power Distribution Diagram	May 12	Mark 34 Mod 2 (Field Engineer Sez).....	Feb. 15
Repainting, Touching Up, and Polishing Electronic		Mark 57 Mod 3 (Field Engineer Sez).....	Feb. 14
Equipment	May 28	Model NMC (Field Engineer Sez).....	Feb. 15
Repair of the Data Converter Synchro in Models		Model NMC-1/2 Replacement Transducers.....	Feb. 31
QHB-a, AN/SQS-10, AN/SQS-11	May 11	Model OKA-1 (Field Engineer Sez).....	Jan. 11
Spare Pinion Gear for DBM-1 Antennas, CBM-66141		Model SV and SV-3 Magnetron Rings.....	Apr. 10
and CBM-66142	May 27	Model TEB Time Interlock Failure.....	Feb. 31
Status of Electronics Maintenance Bulletins.....	May 11	Radio Interference Filters	Feb. 1
SU Radar Antenna Adjustment	May 10	NEL Notes	Apr. 16
Termination of RG-27/U Cable in AN/SQS-10/11		New Attack Sonar Systems.....	Apr. 7
Sonar	May 29	New Books	Feb. 26
Type 3D21A Tubes in AN/UPX-1	May 11	Packaging and Preservation.....	Mar. 30
		QGA (Field Engineer Sez)	Mar. 9
		QHBa (Field Engineer Sez)	Mar. 9
		Replacement of Spur Gear on B-404—Model QHBa	Mar. 31
		Reverse Rotation of Stylus of Motor—Model QDA	Mar. 30
		SG-1b (Field Engineer Sez)	Mar. 8
		Shipboard Electronic Interference	Apr. 12
		Slotted Line Correction Chart (USN USL Notes)..	Feb. 12
		Some Notes on Electronic Reliability in the Fleet.	Jan. 28
		SG-1 (Field Engineer Sez).....	Apr. 9
		SJ-1 (Field Engineer Sez).....	Feb. 14
		SJ-1 (Field Engineer Sez).....	Mar. 8
		SJ-1 (Field Engineer Sez).....	Mar. 9
		SS/SV-1 Console Meter Illumination Lamps.....	Feb. 27
		SS/SV-1 Console Sweep Troubles.....	Jan. 10
		ST Instability When Switch—Over from SJ-1 is	
		Made	Feb. 27
		Standardization of Communication Equipment In-	
		spectations Aboard Ships	Mar. 10
		SV Modulation Networks	Jan. 32
		SV-1 (CXFU) (Field Engineer Sez).....	Feb. 15
		SX (Field Engineer Sez).....	Mar. 8
		TBL-12 (Field Engineer Sez).....	Mar. 9
		TCS-15 (Field Engineer Sez).....	Jan. 11
		Tentative Procedure for Conducting Interference	
		Surveys at Naval Shore Establishments.....	Jan. 16
		Test Cables for AN/URR-13 Receivers.....	Feb. 17
		Training Film on Safety	Apr. 32
		Training Films on Radiosonde and Communication	
		Switchboards	Mar. 31
		Training of Electronics Personnel	Mar. 17
		Transistors	Mar. 14
		Troubles with Relay Contacts	Mar. 20
		Underwater Sound	Jan. 1
		USN USL Notes	Feb. 12
		USN USL Notes	Mar. 18
		Variable Depth Sonar	Apr. 1
		WCA Sonar (Field Engineer Sez).....	Apr. 9
		VF (Field Engineer Sez).....	Apr. 8

The remaining index covers the January 1952 through April 1952 issues of Volume 7. The index to Volume 6, July 1950 through December 1951, appears in the January 1952 ELECTRON.

AN/SPS-6A and AN/SPS-6B Radar Equipment..	Mar. 31
AN/URM-25 Defective Wiring	Jan. 26
Care of Electron Tubes	Feb. 28
Checking Percentage of Modulation of TDZ Trans-	
mitter	Feb. 16
Condition Your Magnetrons	Mar. 13
Conical-scan Tracking Hydrophone (NEL Notes)..	Apr. 16
CXFU (SV-1) (Field Engineer Sez).....	Feb. 15
Electron Tube Replacement Considerations.....	Mar. 23
Electronics in the New Fleet	Apr. 24
Electronics Maintenance Parts System and Con-	
version	Mar. 1
Envelopes for Electronics Failure Report.....	Feb. 17
Equipment Log Books Obsolete	Feb. 27
Error in Model OKA-1 Instruction Book	Mar. 31
Failures—Model SG-1b Antenna	Feb. 31
F.C. No. 1 for the Model OKA-1.....	Feb. 31
Field Engineer Sez	Jan. 11
Field Engineer Sez	Feb. 14
Field Engineer Sez	Mar. 8
Field Engineer Sez	Apr. 8
Fuses!! Fuses!! Fuses!!	Feb. 17
Hazard in TV-4/U Tube Tester in Test-Tool Set	
AN/USM-3	Mar. 23
High Voltage Break Down Precautions for Pulse	
Analyzer AN/SLA-1	Apr. 11
Hoisting Bathythermographs	Apr. 32
Hybrid Ring, The	Feb. 18

PART 2 • CLASSIFIED

RESTRICTED

COMMUNICATIONS EQUIPMENTS

AN/URM-25 Defective Wiring	Jan. 26
AN/URR-13 Receivers, Test Cables for.....	Feb. 17
TBL-12 (Field Engineer Sez).....	Mar. 9
TCS-15 (Field Engineer Sez).....	Jan. 11
TDZ Transmitter, Checking Percentage of Modulation of	Feb. 16
TEB Time Interlock Failure	Feb. 31
Communication Equipment Inspections Aboard Ships, Standardization of	Mar. 10

RADAR

AN/SPS-6A and AN/SPS-6B Radar Equipment... ..	Mar. 31
Mark 10 Radar Identification System.....	Apr. 18
Mark 10/IFF (Field Engineer Sez).....	Apr. 8
Mark 25/2 (Field Engineer Sez).....	Apr. 9
Mark 34 Mod 2 (Field Engineer Sez).....	Feb. 15
Mark 57 Mod 3 (Field Engineer Sez).....	Feb. 14
SG-1 (Field Engineer Sez).....	Apr. 9
SG-1b Antenna—Failures	Feb. 31
SG-1b (Field Engineer Sez).....	Mar. 8
SS Crystal Current, Loss of	Feb. 30
SS/SV-1 Console Meter Illumination Lamps.....	Feb. 27
SS/SV-1 Console Sweep Troubles.....	Jan. 10
SV and SV-3 Magnetron Rings.....	Apr. 10
SV Modulation Networks	Jan. 32
SV-1 (CXFU) (Field Engineer Sez).....	Feb. 15
SX (Field Engineer Sez).....	Mar. 8
VF (Field Engineer Sez).....	Apr. 8
Hybrid Ring, The	Feb. 18

SONAR

ODA—Reverse Rotation of Stylus of Motor.....	Mar. 30
QGA (Field Engineer Sez).....	Mar. 9
QHBa (Field Engineer Sez).....	Mar. 9
QHBa—Replacement of Spur Gear on B-404.....	Mar. 31
NMC (Field Engineer Sez).....	Feb. 15
NMC-1/2 Replacement Transducers	Feb. 31
OKA-1 (Field Engineer Sez).....	Jan. 11
OKA-1, F.C. No. 1 for	Feb. 31
OKA-1 Instruction Book, Error in	Mar. 31
SJ-1 (Field Engineer Sez).....	Feb. 14
SJ-1 (Field Engineer Sez).....	Mar. 8
SJ-1 (Field Engineer Sez).....	Mar. 9
ST Instability When Switch-Over from SJ-1 is Made	Feb. 27
WCA Sonar (Field Engineer Sez).....	Apr. 9

General:

Bathythermographs, Hoisting	Apr. 32
Hydrophone, Conical-scan Tracking (NEL Notes).....	Apr. 16
New Attack Sonar Systems	Apr. 7
Slotted Line Correction Chart (USN USL Notes).....	Feb. 12
Submarine Signal Company 896 Commercial Fathometers, Maintenance Parts for	Mar. 23
Under Water Sound	Jan. 1
Variable Depth Sonar	Apr. 1

MISCELLANEOUS

Tubes:

Electron Tube Replacement Considerations.....	Mar. 23
Electron Tubes, Care of	Feb. 28
Magnetrons, Condition Your	Mar. 13
Ship-board Facsimile Equipment, Loctal Tubes for.....	Mar. 23

Letters to the Editor:

Letters to the Editor	Jan. 27
Letter to the Editor	Feb. 32
Letters to the Editor	Mar. 32

Field Engineer Sez:

Field Engineer Sez	Jan. 11
Field Engineer Sez	Feb. 14
Field Engineer Sez	Mar. 8
Field Engineer Sez	Apr. 8

General:

AS-393 (XN-1)/BLR Antenna Assembly, Maintenance of	Jan. 12
Communication Switchboards and Radiosonde, Training Films on	Mar. 31
Electronics Failure Report, Envelopes for.....	Feb. 17
Electronics in the New Fleet	Apr. 24
Electronics Maintenance Parts, System and Conversion	Mar. 1
Electronics Personnel, Training of	Mar. 17
Electronic Reliability in the Fleet, Some Notes on.....	Jan. 28
Equipment Log Books Obsolete	Feb. 27
Fuses!! Fuses!! Fuses!!	Feb. 17
Hybrid Ring, The	Feb. 18
Interference Surveys at Naval Shore Establishments, Tentative Procedure for Conducting	Jan. 16
NEL Notes	Apr. 16
New Books	Feb. 26
Packaging and Preservation	Mar. 30
Pulse Analyzer AN/SLA-1, High voltage Break Down Precautions for	Apr. 11
Radio Interference Filters	Feb. 1
Radiosonde and Communications Switchboards, Training Films on	Mar. 31
Relay Contacts, Troubles with	Mar. 20
Shipboard Electronic Interference	Apr. 12
ST Instability When Switch-over from SJ-1 is Made	Feb. 27
Training Film on Safety	Apr. 32
Transistors	Mar. 14
TV-4/U Tube Tester in Test-Tool Set AN/USM-3, Hazard in	Mar. 23

Back Copies of ELECTRON (July 1945 through May 1952) are in stock and will be supplied to all Naval activities upon request. A limited number of binders for Volumes 1 through 6 are also available.

LIST OF NAVAL ELECTRONIC EQUIPMENT

The List of Naval Electronic Equipment, NAVSHIPS 900,123(A) contains descriptive data on all equipments to which Navy Model Letters and AN model letters (Navy developed only) have been as-

signed prior to 1 July 1951. This revised edition replaces NAVSHIPS 900,123 and supplement NAVSHIPS 900,123-1 and will be distributed to the holders of NAVSHIPS 900,123 during May 1952.

RESTRICTED 31