19 March 1991 REV: 30 July 1991

To: P. Buck

- Re: Production Test Procedures ALL ST-8000A Operations
- 1. Make <u>five</u> copies of each procedure.
- 2. Punch all copies (not originals) for 3-hole binder
- 3. Stamp each page of the copies with "APPROVED JULY 30 1991".
- 4. There are five sets of 3-ring binders and tabs. Labels:

MODEM BD - A1 CONTROL BD - A2 KEYPAD - PT723-08001 FR PANEL - A3C POWER SUPPLY - A4 CABLES - A5Wx PCB INST - A6A FINAL ASBLY - A6B TEST FIXTURES ENVIRONMENT TESTS INSTR CALIBRATION

Effective 30 July 1991, a 5th binder is required with all above tabs.

- 5. Install five copy sets and tabs in 1.5" Binders.
- 6. Place attached labels on front and edge of binders.
- 7. Distribute:

ORIGINALS: Configuration Control (GWH)COPY #1:Configuration Manager (GWH)COPY #2:Production Test (MT)COPY #3:Quality Assurance (SH)COPY #4:Engineering (RD)COPY #5:Production Test (TLS)

G. W. Henry Configuration Manager

(319TST.DOC; Rev: 910730)